

## HAAS C.N.C. MILL PREPARATORY FUNCTIONS

MODAL  
NON-MODAL  
DEFAULT \*  
OPTIONAL \*\*

<b>G00*</b> RAPID POSITIONING MOTION (X,Y,Z,A,B) (SETTING 10, 56, 101)	<b>G73</b> HIGH SPEED PECK DRILL CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,P,R,L,F) (SETTING 22, 52)
<b>G01</b> LINEAR INTERPOLATION MOTION (X,Y,Z,A,B,F)	<b>G74</b> REVERSE TAPPING CANNED CYCLE (X,Y,A,B,Z,J,R,L,F) (SETTING 130, 133)
<b>G02</b> CIRCULAR INTERPOLATION MOTION CW (X,Y,Z,A,I,J,K,R,F)	<b>G76</b> FINE BORING CANNED CYCLE (X,Y,A,B,Z,I,J,P,Q,R,L,F) (SETTING 27)
<b>G03</b> CIRCULAR INTERPOLATION MOTION CCW (X,Y,Z,A,I,J,K,R,F)	<b>G77</b> BACK BORE CANNED CYCLE (X,Y,A,B,Z,I,J,Q,R,L,F) (SETTING 27)
<b>G04</b> DWELL (P) (P=seconds*, *milliseconds)	<b>G80*</b> CANCEL CANNED CYCLE (SETTING 56)
<b>G09</b> EXACT STOP, NON-MODAL	<b>G81</b> DRILL CANNED CYCLE (X,Y,A,B,Z,R,L,F)
<b>G10</b> PROGRAMMABLE OFFSET SETTING (X,Y,Z,A,L,P,R)	<b>G82</b> SPOT DRILL / COUNTERBORE CANNED CYCLE (X,Y,A,B,Z,P,R,L,F)
<b>G12</b> CW CIRCULAR POCKET MILLING (Z,I,K,Q,D,L,F)	<b>G83</b> PECK DRILL DEEP HOLE CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,P,R,L,F) (SETTING 22, 52)
<b>G13</b> CCW CIRCULAR POCKET MILLING (Z,I,K,Q,D,L,F)	<b>G84</b> TAPPING CANNED CYCLE (X,Y,A,B,Z,J,R,L,F) (SETTING 130, 133)
<b>G17*</b> CIRCULAR MOTION XY PLANE SELECTION (G02 or G03) (SETTING 56)	<b>G85</b> BORE IN-BORE OUT CANNED CYCLE (X,Y,A,B,Z,R,L,F)
<b>G18</b> CIRCULAR MOTION ZX PLANE SELECTION (G02 or G03)	<b>G86</b> BORE IN-STOP-RAPID OUT CANNED CYCLE (X,Y,A,B,Z,R,L,F)
<b>G19</b> CIRCULAR MOTION YZ PLANE SELECTION (G02 or G03)	<b>G87</b> BORE IN-MANUAL RETRACT CANNED CYCLE (X,Y,A,B,Z,R,L,F)
<b>G20*</b> VERIFY INCH COORDINATE POSITIONING (SETTING 9, set to INCH)	<b>G88</b> BORE IN-DWELL-MANUAL RETRACT CANNED CYCLE (X,Y,A,B,Z,P,R,L,F)
<b>G21</b> VERIFY METRIC COORDINATE POSITIONING (SETTING 9 set to METRIC)	<b>G89</b> BORE IN-DWELL-BORE OUT (X,Y,A,B,Z,P,R,L,F)
<b>G28</b> MACHINE ZERO RETURN THRU REF. POINT (X,Y,Z,A,B) (SETTING 108)	<b>G90*</b> ABSOLUTE POSITIONING COMMAND
<b>G29</b> MOVE TO LOCATION THROUGH G28 REF. POINT (X,Y,Z,A,B)	<b>G91</b> INCREMENTAL POSITIONING COMMAND (SETTING 29)
<b>G31**</b> FEED UNTIL SKIP FUNCTION (X,Y,Z,A,B,F)	<b>G92</b> GLOBAL WORK COORDINATE SYSTEM SHIFT (FANUC) (HAAS) (SETTING 33)
<b>G35**</b> AUTOMATIC TOOL DIAMETER MEASUREMENT (D,H,Z,F)	<b>G92</b> SET WORK COORDINATE VALUE (YASNAC) (SETTING 33)
<b>G36**</b> AUTOMATIC WORK OFFSET MEASUREMENT (X,Y,Z,A,B,I,J,K,F)	<b>G93</b> INVERSE TIME FEED MODE ON
<b>G37**</b> AUTOMATIC TOOL LENGTH MEASUREMENT (D,H,Z,F)	<b>G94*</b> INVERSE TIME FEED MODE OFF / FEED PER MINUTE ON (SETTING 56)
<b>G40*</b> CUTTER COMP CANCEL G41/G42/G141 (X,Y)	<b>G95</b> FEED PER REVOLUTION (SETTING 9, 56)
<b>G41</b> 2D CUTTER COMPENSATION, LEFT (X,Y,D) (SETTING 40, 43, 44, 58)	<b>G98*</b> CANNED CYCLE INITIAL POINT RETURN (SETTING 56)
<b>G42</b> 2D CUTTER COMPENSATION, RIGHT (X,Y,D) (SETTING 40, 43, 44, 58)	<b>G99</b> CANNED CYCLE "R" PLANE RETURN
<b>G43</b> TOOL LENGTH COMPENSATION+ (H,Z) (SETTING 15)	<b>G100</b> MIRROR IMAGE G101 CANCEL
<b>G44</b> TOOL LENGTH COMPENSATION- (H,Z) (SETTING 15)	<b>G101</b> MIRROR IMAGE (X,Y,Z,A,B) (SETTING 45, 46, 47, 48, 80)
<b>G47</b> TEXT ENGRAVING (X,Y,Z,R,I,J,P,E,F) (Macro Variable 599 Change Serial #)	<b>G102</b> PROGRAMMABLE OUTPUT TO RS-232 (X,Y,Z,A,B)
<b>G49*</b> TOOL LENGTH COMPENSATION CANCEL G43/G44/G143 (SETTING 56)	<b>G103</b> LIMIT BLOCK LOOKAHEAD (P0-P15 for number control looks ahead)
<b>G50*</b> SCALING G51 CANCEL (SETTING 56)	<b>G107</b> CYLINDRICAL MAPPING (X,Y,Z,A,Q,R)
<b>G51**</b> SCALING (X,Y,Z,P) (SETTING 71)	<b>G110-G129</b> WORK OFFSET POSITIONING COORDINATE #7-26
<b>G52</b> WORK OFFSET POSITIONING COORDINATE (SETTING 33, YASNAC)	<b>G136**</b> AUTOMATIC WORK OFFSET CENTER MEASUREMENT
<b>G52</b> GLOBAL WORK COORDINATE OFFSET SHIFT (SETTING 33, FANUC)	<b>G141</b> 3D+ CUTTER COMPENSATION (X,Y,Z,I,J,K,D,F)
<b>G52</b> GLOBAL WORK COORDINATE OFFSET SHIFT (SETTING 33, HAAS)	<b>G143**</b> 5-AXIS TOOL LENGTH COMPENSATION+ (X,Y,Z,A,B,H) (SETTING 15, 117)
<b>G53</b> MACHINE ZERO XYZ POSITIONING, NON-MODAL (X,Y,Z,A,B)	<b>G150</b> GENERAL PURPOSE POCKET MILLING (X,Y,P,Z,I,J,K,Q,D,R,L,S,F)
<b>G54*</b> WORK OFFSET POSITIONING COORDINATE #1 (SETTING 56)	<b>G153**</b> 5-AXIS HIGH SPEED PECK DRILL CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,P,E,L,F) (SETTING 22)
<b>G55</b> WORK OFFSET POSITIONING COORDINATE #2	<b>G154**</b> SELECT WORK OFFSET POSITIONING COORDINATE P1-99 (P)
<b>G56</b> WORK OFFSET POSITIONING COORDINATE #3	<b>G155**</b> 5-AXIS REVERSE TAPPING CANNED CYCLE (X,Y,A,B,Z,J,E,L,F)
<b>G57</b> WORK OFFSET POSITIONING COORDINATE #4	<b>G161**</b> 5-AXIS DRILL CANNED CYCLE (X,Y,A,B,Z,E,L,F)
<b>G58</b> WORK OFFSET POSITIONING COORDINATE #5	<b>G162**</b> 5-AXIS SPOT DRILL / COUNTERBORE CANNED CYCLE (X,Y,A,B,Z,P,E,L,F)
<b>G59</b> WORK OFFSET POSITIONING COORDINATE #6	<b>G163**</b> 5-AXIS PECK DRILL CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,P,E,L,F) (SETTING 22)
<b>G60</b> UNI-DIRECTIONAL POSITIONING (X,Y,Z,A,B) (SETTING 35)	<b>G164**</b> 5-AXIS TAPPING CANNED CYCLE (X,Y,A,B,Z,J,E,L,F)
<b>G61</b> EXACT STOP, MODAL (X,Y,Z,A,B)	<b>G165**</b> 5-AXIS BORE IN, BORE OUT CANNED CYCLE (X,Y,A,B,Z,E,L,F)
<b>G64*</b> EXACT STOP G61 CANCEL (SETTING 56)	<b>G166**</b> 5-AXIS BORE IN, STOP, RAPID OUT CANNED CYCLE (X,Y,A,B,Z,E,L,F)
<b>G65**</b> MACRO SUB-ROUTINE CALL	<b>G169**</b> 5-AXIS BORE IN, DWELL, BORE OUT (X,Y,A,B,Z,P,E,L,F)
<b>G68**</b> ROTATION (G17,G18,G19,X,Y,Z,R) (OPTION) (SETTING 72, 73)	<b>G174</b> NON-VERTICAL RIGID TAPPING CCW (X,Y,Z,F)
<b>G69*</b> ROTATION G68 CANCEL (SETTING 56)	<b>G184</b> NON-VERTICAL RIGID TAPPING CW (X,Y,Z,F)
<b>G70</b> BOLT HOLE CIRCLE with a CANNED CYCLE (I,J,L)	<b>G187</b> ACCURACY CONTROL FOR HIGH SPEED MACHINING (E) (SETTING 85)
<b>G71</b> BOLT HOLE ARC with a CANNED CYCLE (I,J,K,L)	<b>G188</b> G188 GET PROGRAM FROM PST (Program Schedule Table)
<b>G72</b> BOLT HOLES ALONG AN ANGLE with a CANNED CYCLE (I,J,L)	

*Note: These G and M codes are useful reference information, on a desk, or at the machine. They're great to have laminated with G codes on one side and M codes on the other. As a suggestion; get 90lb. white cardstock and print G-codes on one side and M-codes on the other. Cut out the square section and go to your local printer to get them laminated.*

## HAAS C.N.C. MILL MISCELLANEOUS FUNCTIONS

OPTION\*\*

M00	PROGRAM STOP (SETTING 39, 42)	M50**	EXECUTE PALLET CHANGE (P) (SETTING 121 thru 129)
M01	OPTIONAL PROGRAM STOP (SETTING 17, 39)	M51-M58	OPTIONAL USER M CODE SET
M02	PROGRAM END (SETTING 39)	M59	OUTPUT RELAY SET (N)
M03	SPINDLE ON CLOCKWISE (S) (SETTING 144)	M61-M68	OPTIONAL USER M CODE CLEAR
M04	SPINDLE ON COUNTERCLOCKWISE (S) (SETTING 144)	M69	OUTPUT RELAY CLEAR (N)
M05	SPINDLE STOP	M75	SET G35 OR G136 REFERENCE POINT
M06	TOOL CHANGE (T) (SETTING 42, 87, 155)	M76	CONTROL DISPLAY INACTIVE
M08	COOLANT ON (SETTING 32)	M77	CONTROL DISPLAY ACTIVE
M09	COOLANT OFF	M78	ALARM IF SKIP SIGNAL FOUND
M10**	4th AXIS BRAKE ON	M79	ALARM IF SKIP SIGNAL NOT FOUND
M11**	4th AXIS BRAKE RELEASE	M80**	AUTOMATIC DOOR OPEN (SETTING 131)
M12**	5th AXIS BRAKE ON	M81**	AUTOMATIC DOOR CLOSE (SETTING 131)
M13**	5th AXIS BRAKE RELEASE	M82	TOOL UNCLAMP
M16	TOOL CHANGE (T) (same as M06)	M83**	AUTO AIR JET ON
M17**	APC PALLET UNCLAMP and OPEN APC DOOR	M84**	AUTO AIR JET OFF
M18**	APC PALLET CLAMP and CLOSE DOOR	M86	TOOL CLAMP
M19	ORIENT SPINDLE (P,R values optional)	M88**	COOLANT THROUGH SPINDLE ON (SETTING 32)
M21-M28	OPTIONAL USER M CODE INTERFACE WITH M-FIN SIGNAL	M89**	COOLANT THROUGH SPINDLE OFF (SETTING 32)
M30	PROGRAM END AND RESET (SETTING 2, 39, 56, 83)	M95	SLEEP MODE
M31	CHIP AUGER FORWARD (SETTING 114, 115)	M96	JUMP IF NO INPUT (P,Q)
M33	CHIP AUGER STOP	M97	LOCAL SUB-PROGRAM CALL (P,L)
M34	COOLANT SPIGOT POSITION DOWN, INCREMENT (+1)	M98	SUB-PROGRAM CALL (P,L)
M35	COOLANT SPIGOT POSITION UP, DECREMENT (-1)	M99	SUB/LOCALSUB-PROGRAM / RETURN OR LOOP (P) (SETTING 118)
M36**	PALLET PART READY (P)	M101	MOM (Minimum Oil Machining) CANNED CYCLE MODE (I)
M39	ROTATE TOOL TURRET (T#) (SETTING 86)	M102	MOM MODE (I,J)
M41	SPINDLE LOW GEAR OVERRIDE	M103	MOM MODE CANCEL
M42	SPINDLE HIGH GEAR OVERRIDE	M109**	INTERACTIVE USER INPUT (P)

All **M** codes are effective or cause an action at the end of the block and only one **M** code is allowed in each block.



Haas Automation Inc.

Updated on 1-01-06

*Note: These G and M codes are useful reference information, on a desk, or at the machine. They're great to have laminated with G codes on one side and M codes on the other. As a suggestion; get 90lb. white cardstock and print G-codes on one side and M-codes on the other. Cut out the square section and go to your local printer to get them laminated.*