



HAAS CARBIDE CUT-OFF INSERTS

Cut-Off Inserts Feeds and Speeds

HaasTooling.com

Haas Cut-Off Inserts

How To Use This Chart:

- 1) Select your material in the ISO colored chart
- 2) Select your Insert Cutting Width in the columns
- 3) Start with the middle range of the recommended sfm (vc) and feed (inch/rev)
 - Adjust the sfm and/or feed rate based on your cutting conditions.
 - For Non-ferrous metals a pecking cycle is recommended for help with breaking the chips

ISO	VDI 3323	Material Description		Insert Grade	Cutting Width (inch)		
				HU30	0.079	0.118	0.157
P	P1-5	Non-alloy steel	●	Cutting Speed (vc = sfm)	260 - 590	260 - 590	260 - 590
				Feed (fn = lpr)	0.001 - 0.006	0.001 - 0.008	0.003 - 0.012
P	P6-9	Low alloy steel	●	Cutting Speed (vc = sfm)	230 - 490	230 - 490	230 - 490
				Feed (fn = lpr)	0.001 - 0.006	0.001 - 0.008	0.003 - 0.012
M	M12-14	Stainless steel	●	Cutting Speed (vc = sfm)	200 - 460	200 - 460	200 - 460
				Feed (fn = lpr)	0.001 - 0.004	0.001 - 0.006	0.003 - 0.010
K	K15-20	Grey cast iron	●	Cutting Speed (vc = sfm)	160 - 330	160 - 330	160 - 330
				Feed (fn = lpr)	0.002 - 0.005	0.004 - 0.010	0.004 - 0.012
N	N21-28	Non-ferrous metals	○	Cutting Speed (vc = sfm)	660-1480	660-1480	660-1480
				Feed (fn = lpr)	0.002 - 0.005	0.004 - 0.010	0.004 - 0.012

● Optimal ○ Secondary