



Advanced Lathe Training

Training course

www.hfoallendale.com

Table Of Contents	Pages
Machine Safety	3-6
Personal Protection Equipment	4
E-Stop Button and Stopping the Machine	4
Warning Labels and Decals	5
Safe House Keeping	6
Basic Tool Pre-Setter Functions	7-11
Probing Turning Tools	9-11
Dual Spindle Operations	12-16
Common M/G Codes for Secondary Spindles	14
Spindle Sync Sample	14-15
Machining on Sub-Spindle Sample	16
Live Tool Concepts	17-27
Setting Up Live Tools	19-22
Calculations	22-23
Live Tooling G-Codes	24
Live Tooling M-Codes	24
Axial Live Tool Canned Cycles	25
Axial Live Tool Canned Cycle Examples	25-26
Radial Live Tool Canned Cycles	27
Radial Live Tool Canned Cycles Example	27

Machine Safety



Personal Protection Equipment

- Be aware of your surroundings while working on a CNC machine not paying attention is the easiest way to get injured
- Don't wear loose clothing and keep hair ties up
 - They can easily get caught in a rotating spindle or moving parts
 - The machine will **NOT** stop if your hand, arm or leg get stuck inside the machine and can lead to **SERIOUS** injury
- Appropriate eye and ear protection should be worn while working on the machine
 - Some companies will require you to wear them if you are in the shop
- Wear steel-toed shoes to protect your toes from material being dropped on them

E-Stop Button and Stopping the Machine





- The “Emergency Stop” or “E-stop” button will stop all machine motion
 - This is used in an emergency such as if you see a crash about to happen or a crash has just occurred
 - This will stop all axis motion, the spindle and any other motion in the machine
- The “RESET” will stop a program and return it to the first line
 - The machine will not stop until it finishes specific commands such as:
 - Changing a tool
 - Running a tapping cycle
- The “Feed Hold” button will stop the machine axis motion but not the spindle
 - This is good in a non-emergency situation and would like to check where the tool is
 - (Note: This can leave marks where the tool is stopped)
 - This can help avoid breaking a tool that is mid-cut



NEVER ATTEMPT TO BYPASS THE DOOR INTERLOCKS



Warning Labels and Decals

Symbol	Description
	Danger: this symbol means that there is a condition or situation that <i>will cause death or severe injury</i> if you do not follow the given instructions
	Warning: This symbol means that there is a condition or situation that <i>will cause moderate injury</i> if you do not follow the instructions given
	Caution: This symbol means that <i>minor injury or machine damage could occur</i> if you do not follow the instructions given. You may also have to start a produce over if you do not follow the instructions in a caution statement
	Note: This symbol means that the text gives <i>additional information, clarification or helpful hints</i>

Safe House Keeping


- Be sure to clean coolant spills as soon as they are spotted
- Be sure to keep hands clear of the Auger shaft and the Chip Conveyor both inside and outside the machine
- Be very careful when cleaning chips, they are generally very sharp and will cut your hands
- Additionally, be sure to stay clear of the spindle, tool cutting edges are very sharp
- Never use your fingers to check if a tool is sharp and never handle a tool on the cutting edge
- There should be a safety manual in your shop on how your machine shop deals with specific material

Basic Tool Pre-setter Functions



Getting to the Probing Page

1. Go to EDIT
2. Cursor up to VPS
3. Cursor to the right on PROBING
4. Cursor right on TOOL SETTING
5. Cursor right on TURNING TOOLS



Probing Turning Tools

By selecting MANUAL you will be brought to a screen to touch of you tool

1. **PRESS_[F2]_KEY:** This prompt is used to lower the tool probe arm by pressing "F2". Be sure that nothing is in the probe arm path
2. **TOOL_NUMBER:** This will automatically be generated base on the tool in the active cutting position
3. **TOOL_OFFSET_NUMBER:** This will automatically be generated based on the tool in the active cutting position. It can be change to another offset as required
4. **TOOL_TIP:** This is the direction of you tool (3 is the direction of a standard tool)

Variable	Value	Ranges
PRESS_[F2]_KEY	1	
TOOL_NUMBER	1	
TOOL_OFFSET_NUMBER	1	[1 - 99]
TOOL_TIP	3	[1 - 8]
JOG_POSITION_3	Axis Letter + HANDLE JOG	
TOOL_TIP_DIRECTION_3	3	
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

Select TOOL TIP direction. Tool Offsets Page will update once cycle is completed

Probing Turning Tools

By selecting MANUAL you will be brought to a screen to touch of you tool

5. **JOG_POSITION_#:** This is the position you will have to jog your tool to in order to probe it
6. **TOOL_TIP_DIRECTION_#:** Will let you know the order in which the tool will be touched off
7. **X_OFFSET:** This is the previous offset that is in this Tool Offset page
8. **Z_OFFSET:** This is the previous offset that is in the Tool Offset page

Variable	Value	Ranges
PRESS_[F2]_KEY	1	
TOOL_NUMBER	1	
TOOL_OFFSET_NUMBER	1	[1 - 99]
TOOL_TIP	3	[1 - 8]
JOG_POSITION_3	Axis Letter + HANDLE JOG	
TOOL_TIP_DIRECTION_3	3	
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

Press AXIS Letter + HANDLE JOG key and jog tool tip within (.25"/6mm) of probe

Probing Turning Tools

By selecting AUTOMATIC you will be brought to a screen to touch of you tool

- This should only be used if you flipping in insert
1. **TOOL_NUMBER**: This will automatically be generated base on the tool in the active cutting position
 2. **TOOL_OFFSET_NUMBER**: This will automatically be generated based on the tool in the active cutting position. It can be change to another offset as required
 3. **CALIBRATION_DIRECTION_#**: Will let you know the order in which the tool will be touched off
 4. **TOOL_TYPE**: This is the type of tool being probed and is set in the OFFSETS page

Variable	Value	Ranges
TOOL_NUMBER	1	[1 - 12]
TOOL_OFFSET_NUMBER	1	[1 - 99]
CALIBRATION_DIRECTION_3	3	
TOOL_TYPE_OD_TURN	OD_TURN	
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

TOOL TYPE display only. To change go to offsets page

Probing Turning Tools

By selecting AUTOMATIC you will be brought to a screen to touch of you tool

- This should only be used if you flipping in insert
5. **X_OFFSET**: This is the previous offset that is in this Tool Offset page
 6. **Z_OFFSET**: This is the previous offset that is in the Tool Offset page

Variable	Value	Ranges
TOOL_NUMBER	1	[1 - 12]
TOOL_OFFSET_NUMBER	1	[1 - 99]
CALIBRATION_DIRECTION_3	3	
TOOL_TYPE_OD_TURN	OD_TURN	
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

TOOL TYPE display only. To change go to offsets page

Probing Turning Tools

By selecting AUTOMATIC you will be brought to a screen to touch of you tool

- This should only be used if you flipping in insert
1. **TOOL_NUMBER**: This will automatically be generated base on the tool in the active cutting position
 2. **TOOL_OFFSET_NUMBER**: This will automatically be generated based on the tool in the active cutting position. It can be change to another offset as required
 3. **CALIBRATION_DIRECTION_#**: Will let you know the order in which the tool will be touched off
 4. **TOOL_TYPE**: This is the type of tool being probed and is set in the OFFSETs page

Variable	Value	Ranges
TOOL_NUMBER	1	[1 - 12]
TOOL_OFFSET_NUMBER	1	[1 - 99]
CALIBRATION_DIRECTION_3	3	
TOOL_TYPE_OD_TURN	OD_TURN	
WEAR_TOLERANCE	0.005	[0.0 - 0.1]
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

Enter a wear tolerance to determine if the tool is broken

Probing Turning Tools

By selecting BREAK DETECTION you will be brought to a screen to touch of you tool

- This is used to check if a tool is broken or chipped
5. **WEAR_TOLERANCE**: This is the allowable variation in measurement a tool can have. This measurement is in reference to the number in the tool offset page
 6. **X_OFFSET**: This is the previous offset that is in this Tool Offset page
 7. **Z_OFFSET**: This is the previous offset that is in the Tool Offset page

Variable	Value	Ranges
TOOL_NUMBER	1	[1 - 12]
TOOL_OFFSET_NUMBER	1	[1 - 99]
CALIBRATION_DIRECTION_3	3	
TOOL_TYPE_OD_TURN	OD_TURN	
WEAR_TOLERANCE	0.005	[0.0 - 0.1]
X_OFFSET	-11.008077	
Z_OFFSET	-11.230566	

Enter a wear tolerance to determine if the tool is broken



Dual Spindle
Operations


Dual Spindle (DS) or Secondary Spindles

- A DS lathe is a lathe with a second spindle mounted where the tail stock would normally be mounted
- The secondary or sub-spindle is the B axis with the positive direction is the same as the Z-axis
- Clearance becomes very important when you introduce a second spindle

Secondary Spindle Clearance

- When setting up a machine with a secondary spindle it is important to:

- Check the clearance of the main and sub-spindle
- Check for clearance on long sub-spindle tools
- Check live tools for clearance
- If there is a parts catcher, be sure to check for clearance on both spindles
- Be sure to check for clearance when lowering Tool Presetter



Live Tooling

Common M/G Codes for Secondary Spindles

M/G Code	Code Description
M110	Secondary Spindle (Chuck Close)
M111	Secondary Spindle (Chuck Open)
M114	Secondary Spindle (Brake On)
M115	Secondary Spindle (Brake Off)
M143 (P)	Secondary Spindle Forward (P is the spindle speed)
M144 (P)	Secondary Spindle Reverse (P is the spindle speed)
M145	Secondary Spindle Stop
M119 R0.	Secondary Spindle Orientation (R is the orientation in degrees)
G04 P1.	Dwell (P is time of dwell)
G14	Secondary Spindle Swap
G15	Secondary Spindle Swap Cancel
G199	Engage Sync Spindle Control
G198	Disengage Sync Spindle Control

Spindle Sync Sample (G199)

G97 M03 S500 Start Main Spindle
G199 Sync Spindles


- This is often used to cut off parts or to hand off parts from one spindle to another
 - To end spindle sync you must use G198
 - RESET will NOT un-sync the spindles
- When transferring parts
 - Use a slow RPM (ex. S50) [Spindles can be stopped but it is suggested that they are slowly spinning]
 - Bring the B axis close to the end of part
 - Use spindle air or coolant to ensure there are no chips that will be gripped
 - Give time for spindles to sync
 - Once the B axis is in position you may clamp the secondary spindle (M111)
 - Once spindles are sunk and clamped a higher spindle speed may be used to for cutting off part

Spindle Sync Sample (G199)

```
O0005
  G198 Desync – Part should not be clamped on both ends
G97 M03 S50 Start main spindle
G97 M144 S50 Start secondary spindle
G04 P1. Dwell for 1s
  G199 Sync Spindles
G04 P1. Dwell for 1s
  Run program
  G198 Desync – Part should not be clamped on both ends
  M05 Stop main spindle
  M145 Stop secondary spindle
  M30
```

Spindle Sync Sample (G199 R0.)

- Running with R command in the G199 will offset the spindle being synchronized



Machining on Sub - Spindle Sample (G14)


```
G14 Secondary spindle swap
G97 M03 S1000
G99 Feed per rev.
G01 Z-1. F0.02
G15 Cancel secondary spindle swap
```

- The G14 command allows you to cut on the secondary spindle while programming as if you were to cut on the main spindle
- All operations should start with a G14 and end with a G15
 - Alarm 186 Spindle Not Turning is likely because a G14 was forgotten


Live Tool Concepts



Axial Tools vs. Radial Tools




Axial Tool
AXIAL (Face-Working) Tool



Radial Tool
RADIAL (Cross-Working) Tool

Setting Up Radial Tool Holders


1. Install 10mm Ground Pin on the turret
2. Before mounting live tool remove and Thoroughly clean VDI bold. Also clean inside of the VDI holder on the turret
3. Apply thin film of way lube on the internal contact surfaces of the Radial Tool
4. Mount the Radial Tool and snug the adjustment set screws against the dowel pin at a visually-even and centered position
5. Snug VDI Allen bolt to allow for some movement and adjustment of the tool. Ensure that the back face of the tool holder is flush with the face of the turret
6. Position the Y-axis at zero



Adjust Alignment with Set Screws

Setting Up Radial Tool Holders

7. Install a dowel or gauge pin on the holder like you would install the cutting tool
8. Make sure the tool sticks out at least 1.25". This will be used to run the indicator across it to insure parallelism to X-axis
9. Set indicator with a magnetic base on a rigid surface
10. Position the indicator tip on the end point of the pin and zero the indicator dial
11. Sweep the indicator along the pin to measure the parallelism between the pin and X-axis
12. Adjust the set screws until the tool is aligned properly and parallel to the X-axis
13. Tighten VDI allen bolt to recommended to torque (35-45ft-lbs)



Adjust Alignment with Set Screws

Setting Up Axial Tool Holders

1. Before mounting live tool remove and thoroughly clean VDI bolt. Clean the inside of the VDI cavity on the turret
2. Apply thin film of way lube on the internal contact surfaces of the Axial Tool
3. Mount Axial Live tool aligning on alignment pin. Snug the VDI bolt. Ensure the back face of the tool holder is flush to the face of the turret
4. Tighten the VDI bolt to recommended torque (35-45ft-lbs)




Setting up Tools in Live Tooling Holders

1. Insert the tool into an ER-32 collet.
2. Thread the ER-32 collet nut insert into the collet housing over the tool bit and ER-32 collet
3. Place spanner wrench over the pin of the live tool holder and lock it against the collet
4. Engage the teeth of the collet wrench and tighten


Getting to the Probing Page

1. Go to "EDIT"
2. Cursor up to "VPS"
3. Cursor to the right on PROBING
4. Cursor right on TOOL SETTING
5. Cursor right on LIVE TOOLS
6. Cursor right on MANUAL



Radial Live Tool Setting

- Pressing "F2" the probe arm will go down
- "ORIENTATION" is the tool, in this case you will input "R" for a Radial tool
- RADIAL_TOOL_NUMBER is the tool number
- RADIAL_TOOL_OFFSET_NUMBER is the tool offset you'd like to set
- RADIAL_LIVE_TOOL_DIAMETER is the diameter of the tool you would like to probe
- RADIAL_TIP_DIMENSION_X is the tool radius
- RADIAL_TIP_DIMENSION_Z is the distance to hit the max diameter of the tool
- RADIAL_JOG_POSITION is where you need to place the tool to run
- RADIAL_TOOL_MOTION shows the order in which the tool will be probed



Axial Live Tool Setting

- Pressing “F2” the probe arm will go down
- “ORIENTATION” is the tool, in this case you will input “A” for a Axial tool
- AXIAL_TOOL_NUMBER is the tool number
- AXIAL_TOOL_OFFSET_NUMBER is the tool offset you’d like to set
- AXIAL_LIVE_TOOL_DIAMETER is the diameter of the tool you would like to probe
- AXIAL_TIP_DIMENSION_X is the tool radius
- AXIAL_TIP_DIMENSION_Z is the distance to hit the max diameter of the tool
- AXIAL_JOG_POSITION is where you need to place the tool to run
- AXIAL_TOOL_MOTION shows the order in which the tool will be probed

Editor
VPS
Shape Creator
Program Generation

Live Tool Probe Manual Mode

Run in MDI (CYCLE START)

Generate Gcode (F4)

Reset (ORIGIN)

Devices (F2)

Jog Axis+ [HAND JOG]

◀ Back

Variable	Value	Ranges
PRESS_[F2]_KEY		
ORIENTATION	A	A R
AXIAL_TOOL_NUMBER	1	
AXIAL_TOOL_OFFSET_NUMBER	1	[1 - 99]
AXIAL_LIVE_TOOL_DIAMETER	0.5	[0.03 - 2.0]
AXIAL_TIP_DIMENSION_X	0	[0 - 0.5]
AXIAL_TIP_DIMENSION_Z	0	[0 - 1.0]
AXIAL_JOG_POSITION	Axis Letter + HANDLE JOG	
AXIAL_TOOL_MOTION	Display Only	

AXIAL tool motion sequence. Display only.

C-Axis Info

- When programming on the C-axis the feed rate is in inches per min
 - The feed rate is determined by the diameter entered in SETTING 102 (C-axis Diameter)
 - To change unit to degrees/min the lathe must be turned to metric and setting 102 set to 114.5
 - This is the same as $\frac{360}{\pi}$

Calculating Feed Rate in Degrees/min on C-axis

1. Calculate radial move in inches

Circumference of a circle = Diameter(D) * Π



$$= 4 * \Pi = 12.566$$

Distance travelled over $30^\circ = \frac{30}{360} * 12.566 = 1.047$

2. Movement in Z, if any

3. Calculate total movement (Side C)

$$C = \sqrt{A^2 + B^2} = \sqrt{.25^2 + 1.047^2} = 1.0762$$



Calculating Feed Rate in Degrees/min on C-axis



4. Additional Calculations

$$RPM = \frac{3.82 * (S[\text{ft}/\text{min}])}{\text{Diameter}}$$

$$IPM = FPT * T * RPM$$

$$\text{Minutes to move C} = \frac{C}{IPM}$$

$$\text{Feed Rate (degrees/min)} = \frac{\text{Degrees traveled}}{\text{Time in minutes}}$$



Live Tooling G-Codes

G17	Axial or face working cycles (X-Y plane) *Only works when using a G112
G18	Axial or face working cycles (X-Z plane)
G19	All cross working or radial cycles
G98	Feed rates (in/min)
G99	Feed rates (in/rev) Used for tapping cycles
G112	Converts Cartesian coordinate system to Polar system. This allows a program in X-Y coordinates to be read as a X-C interpolation

Live Tooling M-Codes

M14	Clamp Main Spindle
M15	Unclamp Main Spindle
M19	Orient Spindle (Optional) [Ex. M19 P90]
M119	Orient Sub-Spindle
M133	Live Tool Drive Forward
M134	Live Tool Drive Reverse
M135	Live Tool Drive Stop
M154	C-Axis Engage: Turns the C-axis motor on
M155	C-Axis Disengage: Turns C-axis motor off

Axial Live Tool Canned Cycles

<u>Canned Cycle</u>	<u>Cycle Description</u>	<u>Plane Selection</u>	<u>Feed Rate</u>
G81	Drill	G18	G98
G82	Drill with Dwell	G18	G98
G83	Drill with Peck	G18	G98
G95	Rigid Tap	G18	G99
G186	Rigid Tap Left	G18	G99
X-C Axis Milling	Manual Slots	G18	G98
X-Y Axis Milling	Manual Radius	G17	G98
G112	Cartesian to Polar	G17	G98

Axial Live Tool Canned Cycle Example

Drilling with G81

```

O0051
T101
G18 Calling work plane
G54 G00 X3.0 Z0.1
G98 Feed in in/min
M154 C-Axis Engage
C0.0 Rotate C-axis to 0 degrees
M133 P2000 Turn live tool drive forward at 2000RPM
G81 Z-0.8 F40. Axial Drill Cycle
C120. Rotate C-axis to 120. degrees
C240. Rotate C-axis to 240. degrees
G00 G80 Z0.1
M155 C-axis Disengage
M135 Live Tool drive stop
G53 X0.
G53 Z0.
M30
    
```

Axial Live Tool Canned Cycle G112 Example

```
M154 C- Axis Engage
G28 H0 Unwind C-axis
M133 P2650 Live Tool Drive on at 2650
G59 G00 Z0.15 C0. RPM
G59 G00 X0. Y0.
G98
G17 Feeding in In/min
G112 Use X-Y Plane
G01 Z-0.0075 F20. X-Y to X-C interpolation
G41 X.5 F11.5
Y0.25
G03 X0.25 Y0.5 R0.25
G01 X-0.25
G03 X-0.5 Y0.25 R0.25
G01 Y0.25
G03 X0.5 Y-0.25 R0.25
G01 X0.25
```

Axial Live Tool Canned Cycle G112 Example

```
G03 X-0.5 Y0.25 R0.25
G01 Y0.25
G03 X0.5 Y-0.25 R0.25
G01 X0.25
G03 X0.5 Y-0.25
G01 Y0.
G40 X0.
G00 Z0.25 M00
G113 Cancel G112
G18 X-Z Plane
G99 M135
G53 G00 X0.
G53 G00 Z0.
M30
```

Radial Live Tool Canned Cycles

<u>Canned Cycle</u>	<u>Cycle Description</u>	<u>Plane Selection</u>	<u>Feed Rate</u>
G75	Drill with Peck	G19	G98
G241	Drill	G19	G98
G242	Drill with Dwell	G19	G98
G243	Drill with Peck	G19	G98
G195	Radial Rigid Tap	G19	G99
G196	Radial Rigid Tap Left	G19	G99

Radial Live Tool Canned Cycle Example

Drilling with G81

```

G54
G00 G53 Y0. Home Y-axis
G00 G53 X0. Z-7.
T303
M154 Engage C-axis
M133 P2500 Live Tool Drive at 2500 RPM
G19
G98 Feed in In/Min
G00 X5. Z-0.75 Y0.
G243 X2.1 Y0.125 Z-1.3 C35. R4. Q0.25 F20.
X1.85 Y-0.255 Z-0.865 C-75. Q0.25
G00 G80 Z1.
M135 Stop Live Tool Drive
G00 G53 X0. Y0.
G00 G53 Z00
M00
    
```

Resources

Haas Automation, Inc YouTube Channel
HAASCNC.com