

## Probe Service checklist

Technician		Cell#	
Serial Number		Date	
Model			
<b>Probe Type</b>			
Mill Probe			
Lathe Probe			

### Why is the probe being Serviced?

1a. What alarms or error messages are generated?			
1b. Does the alarm reset?	YES	NO	
1c. When do the alarms or error messages occur?	YES	NO	
2. Are any of the probe components physically damaged?	YES	NO	
3. Has the probe been crashed?	YES	NO	

### 4. Describe the symptom:

--

### Mandatory Troubleshooting

#### Answer the following questions for Mill machines.

5. Did you replace the batteries with new ones?	YES	NO	
6. Are the following options enabled, Macros, Rotating – scale, M19?	YES	NO	
7. Have you cleared macro variables, reloaded Renishaw programs, and recalibrated the Probe?	YES	NO	
8. Have you checked the RGB (light sequence) start up sequence and compared it to factory settings?	YES	NO	
9. Have you verified that machine is using OMI-2H receiver? Have you verified that there are three red lights in the receiver at idle mode?	YES	NO	
10. Have you turned on each probe and made sure the machine beeps when the stylus is pressed and made sure the reset button turns the probes off?	YES	NO	
11. If the customer has an older machine that might have OMI/OMI-2, is spindle probe and tool setter set in legacy mode?	YES	NO	
12. Is the machine software up to date? If you answer no, upgrade to the latest software.	YES	NO	Version #
13. If the customer is using VPS when it crashed what template were they using?	YES	NO	
14. Have you described the behavior of the probe that caused the service call in the notes/observations section?	YES	NO	
15. If the tool crashed what type of tool was it? What is its length when the crash happened?	YES	NO	template #
16. Is the machine software up to date? If you answer no, upgrade to the latest software.	YES	NO	type legnth

#### Answer the following questions for Lathe machines.

5. Do the probe arm up / down switches work?	YES	NO	
6. Is the macro option enable?	YES	NO	
7. Have you reloaded the macro programs, and recalibrated the probe?	YES	NO	
8. When manually touching off tool, is feed rate set at .0001 or .001?	YES	NO	
9. Is the tool probe beeping when not in contact with anything? If yes, have you check is the probe hardware is securely mounted?	YES	NO	Version #
10. Is the customer using VPS or manually taking tool offset?	YES	NO	
11. When using the Automatic or Break Detection cycles in VPS, does the tool have offsets?	YES	NO	
12. Are you able to update the tool offset manually into the offset menu?	YES	NO	
13. Is the machine software up to date? If you answer no, upgrade to the latest software.	YES	NO	
14. Is the customer using soft jog axis keys or jog wheel?	YES	NO	
15. Is the OMI cable pointed up or down? If it is pointed up has there been any coolant contamination on the cable or unit?	YES	NO	

### Notes/ Observations:

--

Attach this report, an error report, and any relevent documentation to a service notification in the Haas Service App.