



%
O01877 (ENGRAVE MC-538)

M06 T8 (ENGRAVING TOOL)
M03 S12000
G55 G00 G90 X-1.07 Y0.379
G43 H08 Z0.1
G01 Z0.1 F100.
G187 P3 E0.002

(ENGRAVE PN)
G47 P0 (P/N MC-538) X-1.07 Y0.379 I-35.78 J0.125 R0.1 Z-.004 F80. E40.

G00 G90 Z1.
G53 G00 G90 Z0
G53 G00 G90 Y0
G187
M30
%

TITLE:

**G47 P0
TEXT ENGRAVING**

SIZE DWG. NO.

A

REV

X1

SCALE: 1:2 WEIGHT: