





Shipping Dimensions
















Maintain 3 feet [915mm] clearance to the nearest obstruction around all sides of machine perimeter for maintenance access











3" Extended Z-Axis Clearance

